

**U.S. Senate**  
**Desk Description and Condition Report**

Desk No : **66.00000.006**

Paper Label No.(on shelf bottom): **6**

Painted No. (on bottom): **N/A**

Other identifying labels or marks (specify location): Stretcher: 6, 6, VI / Top: 6 (stamped) /  
Drawer Bottom: outside - No. 18, 24 (chalk), Nov 4, 1950 (pencil) / Drawer Back: 6 (pencil) / Inside Case  
Back: 18 / Inkwell: 51 (pencil)

## Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 3/8	32 5/16		
Width (front)	28	26 1/8	25 1/2	
Width (rear)	26	24 1/8	23 1/2	
Depth	20	20 1/16	19 1/4	9 7/8

\* Note: Dimensions do not include "booster" blocks added to feet or writing top.

## Woods

Primary:	Mahogany <input checked="" type="checkbox"/>
	Mahogany veneer <input checked="" type="checkbox"/>
	Rosewood veneer <input checked="" type="checkbox"/>
Other Wood (specify): _____	
_____	

Character of case mahogany:	Plain <input type="checkbox"/>
	Ribbon <input type="checkbox"/>
	Mottled <input checked="" type="checkbox"/>
	Crotch <input type="checkbox"/>
	Other <input type="checkbox"/>

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior	✓	✓			
Drawer Front	✓				

## Construction Details

Leg:

Wood Type	rosewood crossband	other crossband	no crossband
mahog. veneer	✓		
solid mahogany			
other: _____			

Foot construction: 1-part ☐  
 2-part ☒  
 5-part ☐  
 Other: \_\_\_\_\_

Double bead on edge of leg: Bead: Thick ☒  
 Thin ☐  
 Leg Thickness: 1 3/16"

Shape of cross-stretcher edges: Rounded ☐  
 Rectangular ☒

Spindle type:	Thick	Thin	Other
Number	2	8	

Joinery of lower drawer blade to case sides: single dovetail ☒  
 2 dovetails ☐  
 3 dovetails ☐  
 lap joint ☐  
 other: \_\_\_\_\_

Shelf molding applied: Yes ☐  
 No ☒

Cockbead width on bottom of drawer front: Narrow ☒  
 Full width ☐

Opening in original top for inkwell: Yes ☒  
 No ☐

Roundels: Single piece ("yo-yo" form) ☒  
 Applied boss ☐

Inset distance of single bead on desk back panel: Side: 1 1/4"  
 Top: 7/8"  
 Bottom: 1"

No. of Glue Blocks	Case	Stretch'r	Shelf
Original/Old			2
New/Recent			
Missing			

Interior case-side flush with corner block? Yes ☒  
 No ☐

Width of drawer-opening offset Right : 5/8"  
 Left : 11/16"

## Condition of Desk

### Structure

Previous breaks in structural elements: Yes ☒  
(shown on schematic)  
No ☐

Current split or broken elements: Yes ☒  
(shown on schematic)  
No ☐

Other loose or damaged joinery: Yes ☐  
(describe in narrative)  
No ☒

Damage to drawer front: Extreme ☐  
Moderate ☒  
Minor ☐

Drawer lock: relocated on face Yes ☒  
Drawer lock: resized on inside Yes ☒

Cockbead on drawer front: Damaged ☒  
(show on schematic)  
Missing ☐  
Loose ☐  
Replacements ☒

Replaced drawer-side runners: Yes ☒  
No ☐

Replaced case-side runners: Yes ☒  
No ☐

Drawer bottom pieced-out at back edge: Yes ☒  
No ☐

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear	✓		

Number of loose spindles: No: 1

Number of replaced spindles: No: 2  
(show on schematic)

Replaced veneers and cross-banding: Yes ☒  
(show on schematic)  
No ☐

Missing veneers and cross-banding: Yes ☒  
(show on schematic)  
No ☐

Delaminated/loose veneers & cross-banding: Yes ☒  
(show on schematic)  
No ☐

Shelf supports: Original/old ☒  
New/recent ☐  
Missing ☐

Spindle support board in case: Yes ☐  
No ☒

## Finish

Age	Excellent	Good	Fair	Poor
New			✓	
Old				
Unk.				

Note: Describe finish problems in narrative.

## Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)			
Knob (R)			

Toe cap size:

Right toe: 8

Left toe: 8